Map ID MAP FINDINGS

Direction Distance

Distance EDR ID Number
Elevation Site EDR ID Number

 1461
 MANHOLE #6350
 NY Spills
 S106735942

 East
 IRWIN ST & HAMPTON AV
 N/A

> 1 BROOKLYN, NY

1.843 mi. 9730 ft.

Relative: SPILLS: Higher Name

Higher Name: MANHOLE #6350
Actual: Address: IRWIN ST & HAMPTO

Actual: Address: IRWIN ST & HAMPTON AV 1 ft. City,State,Zip: BROOKLYN, NY

Spill Number/Closed Date: 0409888 / 2005-04-29

0409888 Facility ID: Facility Type: ER DER Facility ID: 269910 Site ID: 334699 DEC Region: 2 Spill Cause: Unknown Spill Class: C4 2401 SWIS: Spill Date: 2004-12-04 Investigator: **JHOCONNE** Referred To: Not reported

Reported to Dept: 2004-12-04 CID: 71

Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported

Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0

Date Entered In Computer: 2004-12-05
Spill Record Last Update: 2005-04-29
Spiller Name: ERT DESK
Spiller Company: CON EDISON
Spiller Address: Not reported
Spiller Company: 001
Contact Name: ERT DESK

DEC Memo: "e2mis no. 156463: 12/04/2004 21:20 HRS. F.O.D. REPORTS WHILE

LOCATING FAULT 11B03 AT 21:05 HRS. FOUND APPROX. 25 GAL. UNKNOWN OIL ON APPROX. 500 GAL WATER IN MH-68350. HE STATED THERE WAS AT LEAST 3 OF OIL ON TOP OF WATER AND IT SOUNDS LIKE THERE IS A BLOWN JOINT UNDER THE OIL & WATER, BUT HE CANNOT SEE ANY LEAKING EQUIPMENT IN STRUCTURE. SPILL APPEARS TO BE CONTAINED. NO SEWERS OR WATERWAYS

APPEAR TO BE AFFECTED. LIQUID SAMPLE TAKEN ON E PRIORITY TURNAROUND. CHAIN OF CUSTODY FORM # BB-00547. DUE TO AMOUNT OF OIL, FOD TO REMAIN ON LOCATION PENDING ARRIVAL OF ENV OPS TO START CLEANUP AS 50-499 PPM. 12-05-04 LAB SEQ 04-10065-001 127 PPM. UPDATE 12-06-04 CABLE.

CREW CHIEF KEENE REPORTS CABLE HAS BEEN PULLED OUT AND IN WITHOUT INCIDENT, AWAITING UG TO CUT OUT THE JOINT, TAG REMAINS IN PLACE.

Clean Harbors supplied (2)trucks; a >50ppm Tanker, and a > 50ppm Vactor. The tanker removed the liquids and due to Soupy Mud the Vactor took out some solids; we also removed (3) drums of solids; there is a sump that was found sealed. All drums were picked up by Central Field Services (CFS) Astroia. The structure was double washed with (10) gallons of 760, and (5) gallons of Safe Wash; it is cleaned 100 . I left the Stop Tag in place due to a blown 3c cable at the duct edge which the FOD wrapped in plastic and the Underground and

Page: 1

Map ID MAP FINDINGS
Direction

Distance Elevation Site

Site Database(s) EPA ID Number

the Feeder Control Representative was notified to have the tag removed and update the Environmental Desk when the Joint is cut out and the cable is removed. UPDATE 12-6-04 1450 HRS FLUSH OPERATIONS SUPV. G. WILLIAMS REPORTS, UG IS COMPLETE, JOINT IS CUT, AND TAG NO.

EDR ID Number

42200 HAS BEEN REMOVED FROM THE STRUCTURE. JOB IS 100 "
"25 GAL OF UNKN OIL ON 500 GAL WATER, CONTAINED IN MANHOLE, CLEAN UP

PENDING SAMPLE RESULTS. REFERENCE #156463"

All Materials:

Remarks:

 Site ID:
 334699

 Operable Unit ID:
 1096823

 Operable Unit:
 01

 Material ID:
 576694

 Material Code:
 0066A

Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: 25.00
Units: G
Recovered: .00

Oxygenate: Not reported